

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CAD08B510005	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address McDonnell Douglas 14503 So. Normandie Ave. Torrance Ca 90502			A. State Manifest Document Number 84245823		B. State Generator's ID	
4. Generator's Phone (213) 533 0677			6. US EPA ID Number CAD028409019		C. State Transporter's ID 54297	
5. Transporter 1 Company Name Crosby + Overton			8. US EPA ID Number		D. Transporter's Phone 412 5445	
7. Transporter 2 Company Name			10. US EPA ID Number		E. State Transporter's ID	
9. Designated Facility Name and Site Address Crosby + Overton 1620 W. 16th Long Beach Ca 90813			12. Containers No. Type		F. Transporter's Phone	
			13. Total Quantity		G. State Facility's ID	
			14. Unit Mt/Vol		H. Facility's Phone	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			1. Waste No.			
a. 1. Hazardous Waste, Solid nos. ORME NA 7159			001		00500 P 512	
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above Empty gasoline tank to be cleaned + scraped			K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information use gloves, goggles - respirator. Do not go near open flames or inhale fumes.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.						
Printed/Typed Name Donald C. Gerber			Signature Donald C. Gerber		Date 07/18/85	
17. Transporter 1 Acknowledgement of Receipt of Materials			Date			
Printed/Typed Name RALPH E. TRUJILLO, SR.			Signature Ralph E. Trujillo Sr.		Date 07/18/85	
18. Transporter 2 Acknowledgement or Receipt of Materials			Date			
Printed/Typed Name			Signature		Date	
19. Discrepancy Indication Space TANK CLEANED TO GAS CODE						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name Brian Anthony			Signature Brian Anthony		Date 10/01/85	

Called Crosby & Overton


follow up ^{on} ~~call~~
10-2-85

Larry Boyle

Gas tank 2 y 31

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AD086510005	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address M. L. ... 1503 ...				A. State Manifest Document Number 84245823		
4. Generator's Phone (313) 512-0077				B. State Generator's ID		
5. Transporter 1 Company Name		6. US EPA ID Number		C. State Transporter's ID 34297		
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone		
9. Designated Facility Name and Site Address Crosby, Overton		10. US EPA ID Number		E. State Transporter's ID		
				F. Transporter's Phone		
				G. State Facility's ID		
				H. Facility's Phone		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)				12. Containers No.	13. Total Quantity	14. Unit Wt/Vol
a.				Type		I. Waste No.
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above				K. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information use gloves goggles, respirator, do not get near open flames or inhale fumes.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.						
Printed/Typed Name Donald Gerber				Signature Donald Gerber		Date Month Day Year 11/1/85
17. Transporter 1 Acknowledgement of Receipt of Materials						Date
Printed/Typed Name RAYMOND E. TRUJILLO, SR.				Signature Raymond E. Trujillo Sr.		Month Day Year 11/8/85
18. Transporter 2 Acknowledgement or Receipt of Materials						Date
Printed/Typed Name				Signature		Month Day Year
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name				Signature		Date Month Day Year



CROSBY & OVERTON INC.

1610 WEST 17TH STREET, LONG BEACH, CALIFORNIA 90813
(213) 432-5445

OCTOBER 3 1985

TO WHOM IT MAY CONCERN;

THIS IS TO CERTIFY THAT THE GASOLINE TANK BROUGHT TO CROSBY AND OVERTON, INC.
PLANT 1 (CAD028409019) ON CALIFORNIA HAZARDOUS WASTE MANIFEST # 84245823 WAS CLEANED
TO GAS FREE, SCRAPPED, AND SENT TO WILMINGTON SALVAGE TO BE RECYCLED.

THE METHOD OF TREATMENT WAS DETERMINED TO BE THE MOST ECONOMICALLY PRACTICAL,
AND I HAVE SELECTED THE METHOD OF TREATMENT CURRENTLY AVAILABLE TO ME WHICH MINIMIZES
THE PRESENT AND FUTURE THREAT TO HUMAN HEALTH AND THE ENVIRONMENT.

BRIAN ANTHONY
TSDF SUPERVISOR
CROSBY AND OVERTON, INC.
CAD028409019